MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
					Total-Rs.		41,55,522.00

Certificate

(1) Certified that the contractor has work done satisfactorily,

(2) the contractor has removed the debris from work site

(3) there is no any dept. makings issued to contractor

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಬ್ಬಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Officer-in-charge of work

Date: 21.02.2017

60015 to 60026

P.3088

M.A.R.-57 (Rule 118)

Measurement Book No. D 4016312

Serial No. .....

Name of work .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

From ..... To 13/2/17

60026

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

Kalyannagara

81.70 88.10

Pipeline Road

12 m Rd

14 m Rd

53.20

74.6

71.20

INDEX

Roadway

Asphalt

Roadway

24/10/2017

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಬ್ಬಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Scanned by CamScanner